

CRYSTORAMA

LIGHTING THE WAY FOR SIXTY YEARS



Crystorama.com

ASSEMBLY INSTRUCTION MODEL #FAR-6005-AG

WARNING



Electrical Danger



Turn Power Off




All electrical components must be installed by a licensed electrician in accordance with the National Electric Code and the appropriate local electrical codes.



You will need 4-Cand Bulb
40 Watts Recommended 60 Watts Max
Bulb not included
USE LED BULBS FOR EXTENDED USE
This fixture is Damp rated

How to Install

1. Place the mounting plate over the outlet box and mark the 4 points on the wall surface at the center of 4 holes on the mounting plate.
2. Drill 4 holes at the marked points and insert the wall anchors.
3. Attach the mounting plate over the outlet box using two outlet box screws. Insert the anchor screws into the wall anchors to tighten it.
4. Install the recommended bulbs (not included) into each socket.
5. Insert the glass rod into the slots on the frame.



WARNING: This product can expose you to Lead, which is known to the State of California to cause cancer and/or birth defects or reproductive harm. For more information go to www.P65Warnings.ca.gov

CRYSTORAMA

LIGHTING THE WAY FOR SIXTY YEARS



Crystorama.com

PART NUMBER MODEL #FAR-6005-AG

Part Number

Part Numbers

- A. Mounting Hardware
 - (2) Wire Nut
 - (4) Wall anchor
 - (4) Anchor screw
 - (6) Screws
- (1) Mounting Plate
- (1) Green Ground Screw
- B. (1) Back plate; 21.3"x4"x0.7h; XMO6005AGBKP21.3IN
- C. (4) Socket
- D. (2) Metal rod
- E. (1) Frame
- F. (13) Glass rod; 1.5"Wx4"H; XMO6000GLAROD4IN

